

Mock Test

Metal Inert Gas Metal Active Gas Gas Metal Arc Welder MIG MAG GMAW Optional Flux cored Arc Welder SemiAutomatic

Version- 4.0

Level- 4

CSC/N1335. Follow the Health and Safety Practices at the Work

Q1. Which PPE is essential to prevent arc flash injuries during welding? (5 Marks)

- A. Ear plugs
- B. Welding helmet shield
- C. Steel toe boots
- D. Safety gloves

Q2. How can a welder reduce the risk of fire in the workplace? (5 Marks)

- A. Keep flammable materials away
- B. Work near combustibles
- C. Skip grounding checks
- D. Increase welding voltage

Q3. What is the best practice to maintain proper ventilation during welding? (6 Marks)

- A. Ignore smoke accumulation
- B. Open welding curtains
- C. Use local exhaust system
- D. Work in confined spaces

Q4. How should electrical hazards be minimized during MIG/MAG welding? (6 Marks)

- A. Inspect cables regularly
- B. Wear casual clothing
- C. Touch live wires
- D. Use wet gloves

Q5. What is the correct procedure for handling gas cylinders safely? (8 Marks)

- A. Lay cylinders horizontally
- B. Secure upright position
- C. Open valve fully at once
- D. Store near heat source

CSC/N0209. Manually Weld Metals by Using MIG/MAG Welding

Q6. Which technique ensures proper bead penetration during MIG welding? (5 Marks)

- A. Move torch randomly
- B. Use excessive wire feed
- C. Increase voltage excessively
- D. Maintain correct travel speed

Q7. How can a welder prevent porosity in the weld joint? (5 Marks)

- A. Skip surface cleaning
- B. Weld in drafty area
- C. Ensure proper shielding gas
- D. Remove metal oxide

Q8. What technique minimizes spatter formation during manual MIG or MAG welding tasks? (6 Marks)

- A. Push torch incorrectly
- B. Use excessive voltage
- C. Disturb gas coverage
- D. Maintain short stickout

Q9. How can spatter be minimized during MIG welding? (6 Marks)

- A. Adjust voltage and wire feed
- B. Avoid gas flow
- C. Increase torch distance randomly
- D. Use dry electrodes only

Q10. Which practice improves weld consistency on thin metal sheets? (8 Marks)

- A. Drag the torch aggressively
- B. Skip backing support
- C. Use pulse welding mode
- D. Apply excessive current

CSC/N0201. Manually Cut Metal and Metal Alloys Using Oxy-Fuel Gas

Q11. Which procedure ensures safe oxy-fuel cutting of metals? (5 Marks)

- A. Check regulator settings
- B. Ignore leak inspection
- C. Remove safety goggles
- D. Open cylinder fully

Q12. How can accurate metal cutting be achieved manually? (5 Marks)

- A. Cut without guide
- B. Maintain correct torch angle
- C. Move torch randomly
- D. Use excessive oxygen

Q13. What is the best practice to prevent flashback during cutting? (6 Marks)

- A. Leave cylinder open
- B. Keep torch idle
- C. Increase oxygen pressure
- D. Use flashback arrestor

Q14. How can slag formation be minimized during oxy-fuel cutting? (6 Marks)

- A. Increase flame temperature excessively
- B. Adjust preheat and cutting speed
- C. Skip metal cleaning
- D. Reduce gas flow randomly

Q15. Which action protects the operator from sparks and molten metal? (8 Marks)

- A. Wear flame-resistant clothing
- B. Use cotton shirt only
- C. Ignore surrounding flammables
- D. Stand directly above cut

CSC/N0207. Manually Cut Metal Material Using Plasma Arc

Q16. Which factor ensures precise plasma arc cutting of metal? (5 Marks)

- A. Move torch inconsistently
- B. Skip metal cleaning
- C. Maintain correct arc height
- D. Increase air pressure randomly

Q17. How can operator safety be ensured during plasma cutting? (5 Marks)

- A. Wear protective gear
- B. Stand directly overhead
- C. Use regular clothing
- D. Ignore sparks direction

Q18. What improves edge quality when cutting thick metal sheets? (6 Marks)

- A. Move torch erratically
- B. Adjust travel speed
- C. Increase arc length excessively
- D. Use low amperage only

Q19. How is dross formation minimized in plasma cutting? (6 Marks)

- A. Skip surface prep
- B. Keep torch static
- C. Optimize cutting speed
- D. Increase arc voltage excessively

Q20. Which step prevents torch damage during manual plasma cutting? (8 Marks)

- A. Check consumables regularly
- B. Increase air pressure beyond limit
- C. Use worn nozzle
- D. Skip electrode inspection

DGT/VSQ/N0101. Employability Skills (30 Hours)

Q21. Which skill helps welders resolve complex operational issues effectively? (3 Marks)

- A. Work overtime willingly
- B. Maintain welding equipment
- C. Follow written instructions
- D. Critical thinking ability

Q22. How does teamwork improve welding workshop productivity? (3 Marks)

- A. Coordinate with colleagues
- B. Work independently only
- C. Reduced team communication
- D. Focus solely on own task

Q23. Why is time management important for a welder? (4.5 Marks)

- A. Spend long breaks
- B. Delay task completion
- C. Avoid planning workflow
- D. Meet production deadlines

Q24. How can welders demonstrate professionalism at the workplace? (4.5 Marks)

- A. Follow safety protocols
- B. Use appropriate PPE
- C. Respect team members
- D. Take personal calls

Q25. Why is continuous learning critical in welding careers? (5 Marks)

- A. Limits professional growth
- B. Creates unnecessary stress
- C. Update technical skills
- D. Ignore skill gaps

CSC/N0205. Perform Semi-Automatic Flux Cored Arc Welding (FCAW) Process to Prepare Joints

Q26. Which step ensures proper fusion when performing semi-automatic FCAW welding on thicker joints? (5 Marks)

- A. Maintain correct heat
- B. Reduce travel speed
- C. Random wire feeding
- D. Improper torch angle

Q27. How can slag inclusions be minimized during FCAW welding? (5 Marks)

- A. Move torch inconsistently
- B. Adjust welding parameters
- C. Ignore surface prep
- D. Use low-quality flux wire

Q28. Which adjustment ensures stable arc performance when welding structural joints using FCAW? (6 Marks)

- A. Excessively long arc
- B. Lower shielding flow
- C. Incorrect polarity setup
- D. Set proper voltage

Q29. How can a welder ensure uniform bead appearance in FCAW welding? (6 Marks)

- A. Use inconsistent voltage
- B. Maintain steady travel speed
- C. Skip joint alignment
- D. Vary arc length randomly

Q30. Which practice prevents porosity in semi-automatic FCAW welds? (8 Marks)

- A. Overheat base metal
- B. Hold torch too close
- C. Use proper shielding gas
- D. Increase amperage excessively